



Temporaly roof of Cerezo Palace

Valdastillas, Caceres, Spain / 2012

Structural type
Characteristics
Owner
Client
Scope
Architect

membrane structure
PCV membrane
Junta de Extremadura
Comercial Maritima
detailed design and construction support
Amid cero 9 Arquitectos



PCV membrane structure



C/ Barquillo 23, 2º | 28004 Madrid | España
T. (+34) 917 014 460 | F. (+34) 915 327 864
www.fhecor.com | fhecor@fhecor.es