



# Diagnosis and rehabilitation proposal of the old Thermal Power Plant

Sant Adriá del Besós, Barcelona, Spain / 2017

---

Structural type  
Characteristics  
Client  
Scope

chimney  
3 chimney of 200 m high and a building more of 20.000 m2  
Endesa  
diagnosis and intervention start up

## Description



C/ Barquillo 23, 2º | 28004 Madrid | España  
T. (+34) 917 014 460 | F. (+34) 915 327 864  
[www.fhecor.com](http://www.fhecor.com) | [fhecor@fhecor.es](mailto:fhecor@fhecor.es)